

DBT-12


Auto Service
Battery Street 1
Warsaw, Poland
tel 123456789

Test date: 2016-03-14, 15:22:47


BATTERY TEST

Model:
Serial nr:
Test type: **full**
Voltage: **12.66 V**
Norm: **EN**
Nominal: **480 A**
Measured: **436 A**
Battery temperature: **5 ... 15°C**
Comments:

State of charge




State of health



Test result:
GOOD

STARTING TEST


Start time: **1.34 s**
Voltage: **10.92 V**
Minimum: **9.14 V**



Test result:
NORMAL

CHARGING TEST

Loaded: **14.49 V**
No load: **14.41 V**
Alternator ripple: **37 mV**



Test result
NORMAL